


- LEGEND:**
- PROPOSED ROADWAY RECONSTRUCTION
 - PROPOSED BRIDGE AND APPROACH SLAB
 - EARTHWORK LIMIT
 - SARANAC RIVER
 - DRIVEWAYS

REHABILITATION OF UNION FALLS ROAD
BRIDGE OVER SARANAC RIVER
 PIN 7753.98 B.I.N. 3335670




CLINTON COUNTY
HIGHWAY DEPARTMENT






ABBREVIATION:
 FS - FULL SUPER
 HL - HALF LEVEL
 NC - NORMAL CROWN
 RC - REVERSE CROWN

REHABILITATION OF UNION FALLS ROAD
 BRIDGE OVER SARANAC RIVER
 PIN 7753.98 B.I.N. 3335670



CLINTON COUNTY
 HIGHWAY DEPARTMENT






REHABILITATION OF UNION FALLS ROAD
 BRIDGE OVER SARANAC RIVER
 PIN 7753.98 B.I.N. 3335670

LEGEND:
 - - - - - DETOUR ROUTE




CLINTON COUNTY
 HIGHWAY DEPARTMENT





**TYPICAL SECTION NO. 2
BRIDGE APPROACH SECTION**
 LOCATIONS:
 (SLEEPER SLAB) STA. 14+04.60 TO STA. 14+27.73
 STA. 15+54.26 TO STA. 15+74.95



**TYPICAL SECTION NO. 1
FULL DEPTH RECONSTRUCTION**
 LOCATIONS:
 STA. 11+75.00 TO STA. 14+04.60
 STA. 15+74.95 TO STA. 17+25.00


- LEGEND:**
- PROPOSED ROADWAY RECONSTRUCTION
 - PROPOSED BRIDGE AND APPROACH SLAB
 - EARTHWORK LIMIT
 - SUBBASE, TYPE II

**REHABILITATION OF UNION FALLS ROAD
BRIDGE OVER SARANAC RIVER
PIN 7753.98 B.I.N. 3335670**



CLINTON COUNTY
HIGHWAY DEPARTMENT






PROPOSED BRIDGE SECTION

REHABILITATION OF UNION FALLS ROAD
 BRIDGE OVER SARANAC RIVER
 PIN 7753.98 B.I.N. 3335670



CLINTON COUNTY
 HIGHWAY DEPARTMENT





REHABILITATION OF UNION FALLS ROAD
 BRIDGE OVER SARANAC RIVER
 PIN 7753.98 B.I.N. 3335670



CLINTON COUNTY
 HIGHWAY DEPARTMENT



Department of
 Transportation

